

File Edit Options

Tom Grmer

File Edit Permission

Search: By Name and Company

List of 23 index entries:

Fry's (copy)

ISS/ Gary Kremen

Grunman Systems Support Corpora

Highland Digital

Miken Technology Corp. (copy)

List of 1 selected entries:

Grunman Systems Support Corpora

Call

Add

Mail

Share

Whiteboard

Details

New Call

Call from Daniel L. Applebaum

Accept

Refuse

Add

Call on Hold:

Call on Hold

Detail - Grunman Systems Support Corporation (copy)

Edit

Video Phone

File Edit Options

Telephone

Call **Mail** **Share** **Whiteboard** **Messages**

Video Phone

File Edit Options

Telephone

Call **Mail** **Share** **Whiteboard** **Messages**

Name: Grunman Systems Support Corporation (copy)

Work Phone: 800-876-9130

Home Phone:

Company:

Work Address: 5627 Stoneridge Drive, Suite 310
Pleasanton, CA 94588

Home Address:


Remarks: Sun maintenance

Date Updated: Mon Sep 28 14:00:32 1992

Figure 2A

Video File System: Ausrtzspod/af/af/tmp/OM.1249.7

File Edit




Rewind Size: 0:54 min.

Pause



Tom Gruner
Hub Lake

Video Phone



Poste - Browser (demo-melster - /in box)

File View Options Folders Messages Scripts Help

Current Folder: /in box 10 messages, 9 unread. Compose

File to: Other Folder... Reply: Author Trash Read Unread

U 10-10-91 Dec-91 (No Subject)
U 10-10-91 Dec-91 final report

U Daniel I. Appleb Aug-92 World Income Fund: New Possibilities
U Keith Lantz 26-Oct ACME and Paine-Webber
U Devo Heister 18-Dec 100,000 bushels of OIH at 15-25 premium.
U Jennifer Steel 02-Feb Apologies
U Murray Devo 24-May European FX fluctuations
U Mark Van Note 10-Aug Variable Life Insurance
U Jennifer Steel 20-Aug Atherton selection

Subject: meter measurement tool

From: Lester Ludwig <ll>

Date: Tue May 19 18:41:36 1992

To: lawras


Vicon Video Enclosure
(Press Right Mouse Button for Options)

Share: stlm

Add Save Load Print Text Clear Grab Regrab Out

BOB:

LOOK AT THIS DATA!



• YES! I see the problem

FIGURE 2B




FIGURE 3




Fig. 4




Fig 8A





Fig 8B






FIGURE 12A




FIGURE 12B




FIGURE 13A




FIGURE 13B




FIGURE 14A




FIGURE 14B




FIGURE 15A




FIGURE 15B




FIGURE 16

A = 0 UNIT DELAY
 B = 1 UNIT DELAY
 C = 2 UNITS DELAY
 D = 3 UNITS DELAY

B = 0 UNIT DELAY
 A, C = 1 UNIT DELAY
 D = 2 UNIT DELAY

C = 0 UNIT DELAY
 B, D = 1 UNIT DELAY
 A = 2 UNITS DELAY




FIGURE 17A

A = 0 UNIT DELAY
 B = 1 UNIT DELAY
 C = 2 UNITS DELAY
 D = 3 UNITS DELAY

B = 0 UNIT DELAY
 A, C = 1 UNIT DELAY
 D = 2 UNITS DELAY

C = 0 UNIT DELAY
 B, D = 1 UNIT DELAY
 A = 2 UNITS DELAY




FIGURE 17B




Fig. 18A




Fig. 18B

ADD-ON BOX




Fig. 19




Fig. 20

MLAN SERVER
SOFTWARE MODULES

62




FIG. 21




FIG 22




FIG. 23




FIG. 24




FIG. 25




Fig. 26




Fig. 27



FIGURE 28




FIGURE 29




Figure 30




FIGURE 31A




FIGURE 31B




FIGURE 31C




FIGURE 31D




FIGURE 32




FIGURE 33





FIGURE 34






Figure 38






FIGURE 40





FIGURE 42